

AutoShack Weekly Tip



ASWTJuly122020

TAKING ADVANTAGE OF A WATER PUMP JOB

- Overheating is commonly caused by cooling system malfunction.
- A failed water pump sits on top of the list of the most likely culprits of overheating.
- Water pump replacements can be costly because oftentimes, many other components must be removed to access the water pump.
- These components typically wear together.
- To save yourself some money down the line, have your mechanic inspect the removed components to see if any of them needs to be replaced soon.
- If they are worn, replace them while you are replacing the water pump.

- Click links below to visit/contact us to learn more about us and how we might be able to assist you.
 - t: +233-57-6974225
 - e: ask@autoshackghana.com
 - w: www.autoshackghana.com
 - Shop: www.shop.autoshackghana.com
- A majority of the tip topics are suggested by others based on their experiences.
- Consider helping others to benefit from your experiences by suggesting a topic for our tip bank based on your car troubles, experiences or observations.